



## RESIDENTIAL HOME INSPECTION

1234 Main Street  
Vancouver, WA 98683

Buyer Name  
09/30/2024 9:00AM



Inspector

**Russell Tolle**

*Russell Tolle*

WA 1301, OR 2133, OR CCB 219857, EDI WA-44

(360) 419-5544

[info@45thparallel.com](mailto:info@45thparallel.com)

# TABLE OF CONTENTS

1: Inspection Details	4
2: Exterior	5
3: Roofing	12
4: Garage / Carport	15
5: Interiors	18
6: Structural Components	20
7: Electrical System	23
8: Plumbing System	25
9: Heating / Cooling Systems	31
10: Insulation and Ventilation	36
11: Built-In Kitchen Appliances	39
12: Miscellaneous	41
13: Additional Information	44

## Comment Key and Definitions

The following definitions of comment descriptions represent this inspection report.

All comments by the inspector should be considered before purchasing this home.

Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor. All costs associated with further inspection fees and repair or replacement of item, component or unit should be considered before you purchase the property.

**Satisfactory (SA)** = The item was visually observed or operated if applicable, and if no other comments were made then it appeared to be functioning as intended allowing for normal wear and tear.

**Not Inspected (NI)** = The item or system was not inspected and made no representations of whether or not it was functioning as intended. The reason for not inspecting this item will be stated.

**Not Present (NP)** = This item, component or system was not found or not present in this home or building. It is possible it could be hidden from view during the inspection.

**Repair or Replace (RR)** = The item, component or system is not functioning as intended, needs repair or further inspection by a licensed, qualified contractor. Items, components or system that can be repaired to a satisfactory condition may not need replacement. The RR indication is also used to identify minor repairs and maintenance items needing attention.

## Purpose of Inspection

The home inspection and report is meant to visually inspect and identify 'Material' defects in a home that may affect your decision making and valuation of the home.

The inspection is a snapshot in time, and represents the inspectors findings at that point in time, which may change at any point after the inspection. A material defect is an item that may have a significant, adverse impact on the value of the property, or that poses an unreasonable risk to occupants. Some examples of a material defect are a roof that is at the end of life and has significant observable defects or a safety hazard such as exposed wiring. The fact that a system or component is near, at or beyond the end of its normal useful life is not, in itself, a defect. The home inspection process and report is not technically exhaustive or meant to point out cosmetic and readily apparent deficiencies in a home, and these items will not typically be included in the home inspection report. A home inspection does not require special tools such as moisture meters or infrared cameras, but the inspector may use specialized tools to assist in the inspection to go above and beyond the requirements in the attempt to

provide a more informative inspection report. The inspector is required to visually inspect a representative number of some items such as windows and electrical receptacles, not every single occurrence. The home inspection is a non-invasive inspection and will not use any form of destructive inspection or testing unless specified and agreed upon by the inspection company and the customer.

### Due Diligence

Any recommendation for repair or further review made by the inspector should be accomplished by a licensed, qualified, specialist or contractor, which may make recommendations for repair in addition to what the home inspector has identified. As a courtesy, the inspector may make comments regarding the number of occurrences and locations of defects, however, this is not a technically exhaustive inspection and all locations may not be noticed or mentioned in the report. Photos are used to help illustrate issues, but may not indicate all locations of an issue. It is recommended for a licensed contractor or professional to further review an issue to find all defects or locations. The inspector recommends that you obtain information regarding repairs during your sales contingency period, as these recommendations may affect your valuation of the property.

### Report Adjustments

45th Parallel, LLC reserves the right to make corrections and additions to the inspection report for up to one week following the inspection with proper notification to the customer of any relevant changes made. An example of this would be if the inspector remembers that something that was inadvertently omitted from the initial published report and it is deemed by the inspector to be important and may impact your decision making concerning the property.

### Code Compliance

Inspectors are not attempting to inspect the home for code compliance. Building, plumbing, electrical, and mechanical codes change every few years and can be different on a national, state, and local jurisdiction level. It is not realistic or required for an inspector to know what codes were at the time of construction, and to make recommendations to bring it up to current code standards.

## 1: INSPECTION DETAILS

### Information

---

#### Building type

Detached Single Family, Two story

#### Year built

2008

#### Occupancy status

Vacant

#### Predominant direction facing

#### Weather

North

Cloudy

**Last rain**

More than 3 days ago

**Temperature**

60-65 F

**Ground condition**

Damp, Property has irrigation system

**Present at inspection**

Inspector, Customer representative

**Vacant home information**

This home was vacant at the time of the inspection. Vacant homes pose special challenges in some ways when performing a home inspection in that the major systems of the home have not been under a normal or heavy load for some time. For example, a vacant home has not had a full plumbing load placed on it for a period of time, so finding leaks while running a minimal amount of water during a home inspection may be impossible. A fully occupied home, and depending on the occupancy level, has a very different load put on the various systems such as electrical, plumbing, and HVAC than when it is vacant and during a short home inspection. It is possible that some issues may be noticed later that were not evident during a home inspection which is a minimal amount of time in the home and very light use of the major systems.

## 2: EXTERIOR

		SA	NI	NP	RR
2.1	Wall Cladding, Flashing, and Trim				X
2.2	Doors				X
2.3	Windows	X			
2.4	Decks, Balconies, Stoops, Steps, Porches, Covers and Railings	X			
2.5	Driveways, Patios, Walkways				X
2.6	Vegetation, Grading, Drainage, Retaining Walls	X			
2.7	Eaves, Soffits and Fascias	X			
2.8	Miscellaneous				X

SA = Satisfactory    NI = Not Inspected    NP = Not Present    RR = Repair / Replace

### Information

**Elevation photos**

General elevation photos of the home.



Front



Right side



Rear



Left side

**Appurtenances**

Sidewalk, Covered porch,  
Driveway

**Wall Cladding, Flashing, and Trim: Wall Cladding, Flashing, and Trim:**

**Siding Style**

Panel, Board and batten

**Siding Material**

Fiber cement, Wood trim

**Wall Cladding, Flashing, and Trim: Fiber cement siding information**

Fiber cement is a composite material made of cement reinforced with cellulose fibers. Originally, asbestos was used as the reinforcing material but, due to safety concerns, that was replaced by cellulose in the 1980s. Fiber cement board may come pre-painted or pre-stained or can be done so after its installation. It comes in long planks to be used as lap siding or in large 4x8 sheets.

Fiber cement siding has several benefits since it is resistant to termites, does not rot, is impact resistant, and has fireproof properties. Properly installed and maintained fiber cement siding can last 50 years or more.



**Doors: Change door locks and codes**


**Recommendation:** Change or re-key all locks and garage door codes upon moving into the home for additional security.

**Windows: Window Types**

Thermal/Insulated, Vinyl Clad,  
Single-hung, Sliders, Fixed

**Windows: Weep hole maintenance tip**

Do not cover weep holes with caulk or allow them to be obstructed in any way. Their function is to drain water from the window track and if blocked could allow water to find a way into the wall and cause damage.



Typical weep hole in vinyl clad window

**Driveways, Patios, Walkways: Walkways**

**Driveways, Patios, Walkways: Driveway**

**Driveways, Patios, Walkways: Patios**



## Observations

---

### 2.1.1 Wall Cladding, Flashing, and Trim

 Summary Item

#### **SEALANT MISSING OR GAPPING**

Windows, Siding / trim, Penetrations


**Issue:** There is missing or gapping sealant that can allow water entry and potential damage to the structure.

**Remedy:** Have high quality sealant applied or repaired in areas as necessary to prevent water entry.

**Recommended time frame:** Ideally, prior to significant rainfall



Left side hose bib



Siding trim



Window trim

2.1.2 Wall Cladding, Flashing, and Trim

Summary Item

**WOOD DECAY**

MULTIPLE AREAS, FRONT, RIGHT, REAR  
Trim, Window trim

**Issue:** Wood decay is present in siding or trim on the exterior of the building.

**Remedy:** Have any decayed areas replaced to prevent potential fungal growth, more extensive damage to the structure, and pest intrusion.



Right side trim



Right side trim



Right side trim



Right side trim




Right side trim



Location depicted Right side



Rear window trim



Rear trim



Rear trim



Rear window trim



Rear trim



Rear, Location depicted





Front upper

2.1.3 Wall Cladding, Flashing, and Trim

 Minor Defect / Maintenance / Monitor Item

**SIDING MAINTENANCE NEEDED**

Paint / prep, Seal splits / cracks, Loose nails / panels

**Issue:** The siding needs general maintenance or minor repairs. Make siding repairs promptly to help prevent water intrusion.

**Remedy:** Have the siding repaired or maintenance performed to help prevent water damage to the structure.

**Notes:** Repairs and maintenance is an on-going part of owning a home. Expect to perform yearly inspection, maintenance and repairs to the siding to keep it water tight.

- Repair or install sealant in gapping or missing sealant areas
- Repair any over driven nail holes by caulking / sealing
- Repair failing paint by removing loose paint, priming, and re-painting
- Repair or seal any gaps, splits, in the siding or joints as necessary
- Drive or replace any nails which are coming loose

Pro-active inspection and maintenance will keep your siding in better shape longer and help prevent water damage to the structure.



Left front corner



Front, over walkway




2.1.4 Wall Cladding, Flashing, and Trim

 Minor Defect / Maintenance / Monitor Item

**LOOSE, MISSING, OR DAMAGED TRIM**

**Issue:** The trim is loose or missing in some areas and needs repair. Loose or missing trim could potentially allow water entry and damage to the structure.

**Remedy:** Repair by a contractor or handyman



Right front corner



Trim is loose

2.2.1 Doors

 Minor Defect / Maintenance / Monitor Item

**DOORBELL INOPERABLE**

The front doorbell is broken and does not ring inside the home when you push it. Have it repaired if you like to hear the doorbell.



Rear, South side

2.2.2 Doors

 Minor Defect / Maintenance / Monitor Item

**TRIM PIECE LOOSE ON DOOR**

The rear door facing Rasmussen Street has loose vinyl trim around the window. Repair as necessary or replace.



Loose trim, damaged



2.3.1 Windows

 Minor Defect / Maintenance / Monitor Item

### MISSING OR DAMAGED SCREEN

MULTIPLE AREAS

**Issue:** There are missing or damaged screens for some windows. Screens in good working condition are important to help prevent pests and insects from entering the home. Pests and insects can potentially cause health related issues.

**Remedy:** Have screens repaired or installed as necessary.



2nd Floor bonus room



2nd Floor Bedroom

2.5.1 Driveways, Patios, Walkways

 Safety Item

### TRIP HAZARD

FRONT PUBLIC SIDEWALK, REAR PUBLIC SIDEWALK

**Issue:** Some areas of the walkways are uneven and are a potential trip hazard. Vertical offsets in walkways of approximately 3/8" or greater are noted as trip hazards.

**Remedy:** Have a contractor repair the walkway. Repair is often accomplished by grinding off the concrete to smooth out the surface.



Front public walk away, tree roots have damaged sidewalk



Rear public sidewalk offset



Offset is a trip hazard

2.8.1 Miscellaneous

 Minor Defect / Maintenance / Monitor Item

**FENCING NEEDS REPAIR**

DAMAGED TO LEFT SIDE GATE

While beyond the scope of the home inspection, I like to point out extra little items like fencing that needs repair. The fencing and gates need some repair on this home.



### 3: ROOFING

		SA	NI	NP	RR
3.1	Roof Coverings				X
3.2	Roof Flashing				X
3.3	Skylights, Chimneys and Roof Penetrations	X			
3.4	Gutters and downspouts	X			

SA = Satisfactory    NI = Not Inspected    NP = Not Present    RR = Repair / Replace


#### Information

**Method roof viewed**

Walked roof

**General roof photos**

A few general photos of the roof areas.



**Roof Coverings: Roof covering materials**

3-Tab, Asphalt/Fiberglass

**Roof Coverings: Roof covering layers**

1



### Roof Coverings: Architectural composition shingles

The roof covering is architectural shingles. This type of shingle, with care and maintenance has a typical lifespan of 20-25 years, however various factors can affect the performance.



#### Skylights, Chimneys and Roof Penetrations: Number of chimneys

0

#### Skylights, Chimneys and Roof Penetrations: Chimney (exterior)

N/A

#### Skylights, Chimneys and Roof Penetrations: Number of skylights

0

### Gutters and downspouts: Drainage general info

**Maintenance Tip:** Maintain the home's drainage systems and landscaping for proper water management. Gutters and downspouts should be kept free of debris that can impede water drainage and to prevent over flowing which can deposit large amounts of water next to the home's foundation. Underground drains should be operational and any drainage issues noticed should be repaired right away. Any downspouts not having underground drains should have extensions that deposit water 5 to 6 feet away from the home's foundation. All landscaping, patios, walkways, or surfaces that shed water should slope away from the home. Proper gradient is a 5% slope away from the home which equates to 6 inches of drop in 10 feet.

## Limitations

---

Gutters and downspouts

### UNDERGROUND DRAINS NOT VISIBLE

Underground drainage and runoff systems, if present, are not visible for inspection. I cannot see any underground drains and am unable to determine if they are functional.



## Observations

---



3.1.1 Roof Coverings

Summary Item

**ROOF COVERING NEEDS REPAIRS / MAINTENANCE**

Damaged shingles, Heavy granule loss

**Issue:** The roof covering needs repairs / maintenance to correct the mentioned items. It is important to make roof repairs in a timely manner to prevent leaking and protect the structure.

**Remedy:** Have repairs / maintenance performed by a roofing contractor to protect the structure from water intrusion



Damaged shingle



Damaged shingle



Horizontal cracking of shingles



Horizontal cracking and granule loss of shingles



Heavy granule loose under downspout



Heavy granule loss under downspout

3.1.2 Roof Coverings

Summary Item

**ROOF END OF LIFE**

**Issue:** The roof covering appears to be at the end of its useful life given appearance, and should be reviewed by a roofer for further recommendations regarding time frame and cost for replacement.

**Remedy:** Have a roofer review the roof for recommended time frame for replacement.

**Recommended time frame:** During your contingency period



3.2.1 Roof Flashing


Summary Item

**MISSING OR INADEQUATE KICKOUT FLASHING**

FRONT, REAR

**Issue:** There is missing, damaged, or inadequate kickout (diverter) flashing at some roof / wall intersections. Kickout flashing directs water away from the side wall and into the gutter to prevent water running down and potentially behind the wall cladding causing damage to the structure. Kickout flashing should be a minimum 4x4 inches for proper water management. Older homes did not require it, but it is a very good item to have installed for water management because the roof / wall intersection is a problematic area for water intrusion.

**Remedy:** Have a roofing contractor add / repair a full sized (4x4 inches) kickout flashing properly integrated with step flashing and water resistive barrier to areas not having one or where inadequate / damaged.



Kickout flashing



Undersized and inadequate kick out flashings



Kick out flashing is not properly sealed



Rear



Front

4: GARAGE / CARPORT

		SA	NI	NP	RR
4.1	Garage Ceilings	X			
4.2	Garage Walls	X			
4.3	Garage Floor	X			
4.4	Garage Windows			X	
4.5	Overhead Door(s)				X
4.6	Occupant Door (garage to inside of home)	X			
4.7	Garage Door Operators				X
4.8	Service door			X	
4.9	Garage stairs, steps, railings	X			

SA = Satisfactory    NI = Not Inspected    NP = Not Present    RR = Repair / Replace

Information



**Garage Type**

Two car attached

**Roof Covering**

Same as house

**Siding material**

Same as house

**Siding style**

Same as house

**Garage Floor: Fire safety and attached garages**

Any time an attached garage has appliances such as washer / dryer, refrigerators, water heaters, or other sources of ignition that have an electric motor or open flame that is less than 18 in from the floor, it is good practice to elevate these items 18 from the floor. Open flames or electric motors can generate an ignition source for flammable vapors such as gasoline in the garage. Lots of people put refrigerators and washers and dryers in their garage and in this case it's a good practice to not store any flammable chemicals or park in the garage unless these items are elevated. Often times in homes that we inspect there are appliances in the garage that will be gone when you move in however we point these out for your fire safety education.

**Overhead Door(s): Number of Overhead Garage Doors**

One automatic

**Garage Door Operators: Photo sensors reverse for overhead door**

Reverse door as expected

**Garage Door Operators: Pressure reverse for overhead door**

Not tested

## Limitations

---

General Info

**LIMITATIONS**

Storage items, Shelving, Floor, Walls

## Observations

---

4.5.1 Overhead Door(s)



Minor Defect / Maintenance / Monitor Item

**MANUAL LOCK****INSTALLED ON AUTOMATIC OVERHEAD DOOR**

**Issue:** There is a manual lock installed on the overhead door that has an automatic door opener. If the door opener is operated with the lock engaged, it could damage the door, the opener, and potentially cause the door to come off of the track and fall.

**Remedy:** Remove or disable the lock

**Additional notes:** [Click here to read the \\$800 button push](#)



Manual lock installed on overhead door with opener

4.6.1 Occupant Door (garage to inside of home)




### SELF CLOSE HINGES - UPGRADE RECOMMENDED

**Issue:** There is no self-closing hinges on the garage occupant door that automatically closed the door. Self-closing hinges are a safety feature to help protect against fire and carbon monoxide entry into the home.

**Remedy:** Consider adding self-closing hinges to the garage occupant door for additional fire and CO safety.

**Additional Information:** Current safety standards require them. It may not have been a requirement when this home was built, however, it is a recommended fire safety upgrade and is the current standard. However small children will be present, self-closing doors can be dangerous for children and fingers which could get slammed in the door. This is a personal choice and many people choose to not have self-closing doors when they have small children.



4.7.1 Garage Door Operators



### PHOTO SENSORS INSTALLED TOO HIGH

**Issue:** The photo sensors on the garage door are installed higher than 6" above the garage floor. Manufacturer directions indicate a maximum height of 6" above the floor for safety and to prevent injury.

**Remedy:** Have the photo sensors adjusted to be installed within 6 inches of the floor.

**Recommended time frame:** Immediately if small children will be present



Photo sensors installed too high

4.7.2 Garage Door Operators



### DOOR CONTROLLER INSTALLED TOO LOW

**Issue:** The garage door opener control is installed less than 5 feet tall above the walking surface. Manufacturers specify installation at least 5 feet above the walking surface to avoid small children from operating the door. This is a safety hazard for small children.


**Remedy:** Have the controller raised to be at least 5 feet above walking surface.

**Recommended timeframe:** Immediate if small children will be present

**Additional notes:** We measure from wherever a person would stand to operate the controller such as a landing or step next to the controller.



Typical garage door manufacturer safety sticker



We're a child would stand to operate the door opener



Hoping there is a little over 4 ft above the adjacent walking surface

# 5: INTERIORS

		SA	NI	NP	RR
5.1	Ceilings	X			
5.2	Walls				X
5.3	Floors	X			
5.4	Windows	X			
5.5	Doors	X			
5.6	Steps, Stairways, Balconies, Railings	X			
5.7	Counters, Cabinets, Closets	X			

SA = Satisfactory    NI = Not Inspected    NP = Not Present    RR = Repair / Replace

## Information

### Inspection general information

The inspector will inspect accessible and visible areas of the home. Inspectors do not move personal belongings or furniture and do not climb on personal belongings or furniture to reach areas such as windows or cabinets. In furnished, staged, or lived in homes, some areas may not be visible or accessible during the home inspection, and will not be inspected or commented on.

## Limitations

General Info

### PERSONAL BELONGINGS OR STORAGE LIMITS INSPECTION

Any areas of the home that contain storage items or personal belongings limit the inspection in those areas. Areas not accessible or visible are not inspected or commented on, and could potentially hide unknown issues.

## Observations

5.1.1 Ceilings

### NAIL POPS

 Minor Defect / Maintenance / Monitor Item

There are a few 'nail pops' around the home where the nail heads have pushed the sheetrock / spackle out and has a bump on the ceiling. This is cosmetic in nature and normal to see in most houses at some point. Repair as necessary.



Example



## 5.2.1 Walls



Minor Defect / Maintenance / Monitor Item

**NORMAL  
DRYWALL HAIRLINE CRACKING**

There were some typical hairline cracking in the drywall around the home. This appears cosmetic in nature and is likely due to minor settlement or improper joint preparation. Repair as necessary.



2nd Floor Bathroom

## 5.2.2 Walls




Minor Defect / Maintenance / Monitor Item

**HOLE IN WALL**

2ND FLOOR BEDROOM

**Issue:** There is a hole in the wall that needs repair. Holes in interior walls are in general considered a cosmetic item, however, in places such as under sinks and cabinets holes in walls could allow pest entry and should be sealed.

**Remedy:** Repair as necessary



## 5.2.3 Walls



Minor Defect / Maintenance / Monitor Item

**MOISTURE  
DAMAGE BASEBOARD**

2ND FLOOR HALLWAY BATHROOM

**Issue:** There is moisture damage to a baseboard.

**Remedy:** Have it repaired / replaced.

**Recommended time frame:** When feasible


5.7.1 Counters, Cabinets,  
Closets

Minor Defect / Maintenance / Monitor Item

**SEAL HOLES AROUND PIPES**

KITCHEN SINK

It's a good recommendation to seal any holes around plumbing pipes under sinks to prevent air movement in cavities, to prevent water potentially entering the gaps under the cabinet, and to help prevent pest entry.



# 6: STRUCTURAL COMPONENTS

		SA	NI	NP	RR
6.1	Roof Structure and Attic	X			
6.2	Ceilings (Structural)	X			
6.3	Walls (Structural)	X			
6.4	Floors (Structural)	X			
6.5	Foundations, Basement and Crawlpace	X			
6.6	Columns, Piers and Beams		X		

SA = Satisfactory    NI = Not Inspected    NP = Not Present    RR = Repair / Replace

## Information

### Roof Structure and Attic: Roof-Type

Shed, Gable

### Roof Structure and Attic: Roof Structure

Engineered wood trusses, OSB sheathing



### Roof Structure and Attic: Attic access

Scuttle hole

### Roof Structure and Attic: Attic access location

Laundry / utility room



### Roof Structure and Attic: Method used to observe attic

Walked

### Roof Structure and Attic: Attic #1 general photos

General photos of the attic space.





**Ceilings (Structural): Ceiling Structure**

Top side of ceiling not visible

**Walls (Structural): Wall Structure**

Main wall structure not visible, Wood construction, Strip footings, Pony walls

**Floors (Structural): Floor Structure**

Engineered floor joists

**Foundations, Basement and Crawlspace: Foundation Type**

Crawlspace, Poured concrete

**Foundations, Basement and Crawlspace: Method used to observe Crawlspace**

Crawled

**Foundations, Basement and Crawlspace: Crawlspace #1 general photos**

Some overall general photos of the crawlspace.



**Foundations, Basement and Crawlspace: Crawl space entry location**

Hall closet

**Foundations, Basement and Crawlspace: Typical foundation shrinkage cracks**

There are some typical vertical cracks in the foundation wall. All concrete cracks, and these appear to be typical shrinkage cracks. No action is necessary.

Notes: cracks from hairline to 1/8 inch are generally considered negligible and do not indicate a structural issue. Ensure the downspouts are properly functioning and get water away from the foundation at least 5 feet.



**Columns, Piers and Beams:****Columns or Piers**

Not visible

## Limitations

---

Ceilings (Structural)

**CEILING TOP SIDE NOT VISIBLE - INSULATION**

The ceiling structure is mostly not visible for inspection due to installed insulation in the attic.

---

Walls (Structural)

**WALL STRUCTURE NOT VISIBLE**

The wall structure is mainly not visible or able to be inspected due to wall coverings such as drywall.

---

Floors (Structural)

**FLOOR UNDERSIDE NOT VISIBLE - INSULATION**

The floor structure is not visible for inspection in some areas due to installed insulation.

---

Columns, Piers and Beams

**NOT VISIBLE**

Columns, piers, or beams, if existing, are not visible for inspection.

# 7: ELECTRICAL SYSTEM

		SA	NI	NP	RR
7.1	Service Entrance Conductors	X			
7.2	Service Equipment / Electrical Panels	X			
7.3	Branch Circuit Conductors	X			
7.4	Connected Devices and Fixtures				X
7.5	Polarity and Grounding	X			
7.6	GFCI / AFCI Outlets and Breakers				X
7.7	Smoke Alarms	X			
7.8	Carbon Monoxide Alarms				X

SA = Satisfactory    NI = Not Inspected    NP = Not Present    RR = Repair / Replace

## Information

### Service Entrance Conductors:

#### Service entrance location

Exterior of home, Left side



### Service Entrance Conductors:


#### Service Entrance Conductors

Below ground, Aluminum, 240 volts

### Service Equipment / Electrical Panels: Main panel location

garage

Maintain proper clearance around electrical panels which is 30 inches wide measured either from the centerline (15 inches each way) or from one edge of the panel, 3 feet to the front of the panel, and all the way from 6 feet 6 inches high to the floor. It is important to keep this area clear for working access and for quick access in the event of an emergency.



Working clearance around electrical panels

### Service Equipment / Electrical Panels: Main disconnect location

At main panel

### Service Equipment / Electrical Panels: Panel Type

Circuit breakers

### Service Equipment / Electrical Panels: Panel Manufacturer

SQUARE D





**Service Equipment / Electrical Panels: Main panel capacity**  
200 AMP

**Service Equipment / Electrical Panels: Service grounding conductor**

Appears to be properly grounded, Ground present in panel

### Service Equipment / Electrical Panels: Main panel inspected

The main electrical panel was inspected.



### Branch Circuit Conductors:

#### Branch Wiring Type

NMB (Non-metallic)

### Branch Circuit Conductors:

#### Branch Wiring Material

Copper, Stranded Aluminum

### GFCI / AFCI Outlets and Breakers: Test AFCI / GFCI

I recommend testing any existing AFCI / GFCI breakers or receptacles monthly to ensure proper operation.

### Smoke Alarms: Smoke alarm information

Recommended Immediately: Replace all smoke alarms upon move in unless you know the absolute age. If the detectors are 10 years or older, replace them as recommended by the NFPA (National Fire Protection Agency). Test all smoke alarms upon move in to ensure proper operation, and test monthly or as recommended by the manufacturer. Replace all smoke alarm batteries yearly or immediately upon low battery notification. Please Note: Smoke alarms are not always tested. Alarms are inspected for the presence of absence of alarms. It can be difficult to determine if smoke alarms are working properly. Smoke alarms are not tested if there is a security system. It is recommended to have all dual function smoke alarms of type ionization and photoelectric as they provide the best protection. The safest combination is hardwired plus battery backup dual function detectors. Smoke alarm placement requirements when selling a home varies by state.

### Carbon Monoxide Alarms: Carbon monoxide alarm information

I recommend testing Carbon Monoxide (CO) detectors upon move-in, weekly or per manufacturer directions and changing batteries upon move-in and yearly. Please note that Carbon Monoxide detectors are required in a common area on each level of the home including basements and habitable attics. Replace CO detectors per manufacturer instructions, typically every 5 years. I recommend replacement of CO detectors upon move in unless you know the exact age. Please note that carbon monoxide detectors are not always tested. The absence or presence of detectors is what is inspected.

## Observations

---

7.4.1 Connected Devices and Fixtures

 Minor Defect / Maintenance / Monitor Item

**MISSING KNOB ON FAN SWITCH**

The fan switch at the master bedroom needs to have a knob installed on the metal rheostat control.



7.6.1 GFCI / AFCI Outlets and Breakers

 Safety Item

**AFCI NOT INSTALLED FOR REQUIRED LOCATION**

NO ARC FAULT FOR BEDROOM CIRCUIT, ARC FAULT WAS REQUIRED FOR BEDROOMS IN 2008

In new construction current standards require afci on all 15 and 20 amp breakers for conditioned areas of the home. There is an area with a 15 or 20 amp branch circuit that does not have AFCI protection as required. Have this repaired by an electrician as it is a current safety requirement.



7.8.1 Carbon Monoxide Alarms

 Safety Item

**WA - NO CO ALARM IN REQUIRED AREA**

LOCATION: 2ND FLOOR HALLWAY

**Issue:** There is no carbon monoxide alarm located in a required area.

**Remedy:** Have a CO alarm installed in the required area.

**Recommended time frame:** Immediate

**Additional notes:** in WA, when selling a home, Carbon Monoxide alarms are required in a common area on each level of the home, in the immediate vicinity of sleeping rooms, in basements and habitable attics.

## 8: PLUMBING SYSTEM

		SA	NI	NP	RR
8.1	Drain, Waste and Vent	X			
8.2	Water Supply, Distribution and Fixtures				X
8.3	Hot Water Systems, Controls, Chimneys, Flues and Vents	X			
8.4	Main Water Shut-off	X			
8.5	Fuel Storage and Distribution Systems	X			
8.6	Main Fuel Shut-off	X			
8.7	Sump Pump / Ejector Pump			X	
8.8	Central Vacuum System			X	

SA = Satisfactory    NI = Not Inspected    NP = Not Present    RR = Repair / Replace

## Information

### Drain, Waste and Vent: Waste system type

Appears to be:, Public sewage,  
Unable to determine

### Drain, Waste and Vent: Waste piping material

ABS

### Drain, Waste and Vent: Recommend sewer line inspection

We recommend having a sewer line inspection from the house to the street / septic to determine the condition of the main sewer line. It's a good idea to have one done because any sewer line repairs, if necessary, can be costly depending on the repair and the location.



### Drain, Waste and Vent: Notes regarding testing of fixtures

Overflow drains are not tested during the home inspection as the sinks and bathtubs are not filled to capacity. This is for two reasons. Number one is to reduce the possibility of overflow and water incidents. Secondly overflow drain lines for tubs and sinks, especially in older installations may have dried out cracked rubber seals and a greater possibility of leaking. In general, overflow drains are emergency devices and not meant for daily use. Sinks, tubs, showers, and toilets are tested for normal operation, hot and cold where applicable, and proper drainage. While we do run water at all accessible fixtures during the home inspection, it may not be enough to discover an issue that will only be apparent after moving in and operating the plumbing system under a full working load. The home inspection cannot simulate a full plumbing load on the home. Homes that have been vacant for some time also pose a special challenge in that the plumbing has not been under a full load for however long it has been vacant making it more difficult to spot issues and to predict how the home's plumbing system will perform under a normal full working load.

### Drain, Waste and Vent: Past leaking evident

Staining on multiple drain line areas under the kitchen sink

There are some staining or signs of past leaking at a drain pipe. I did not notice any current leaking. Monitor for any future occurrences.



### Water Supply, Distribution and Fixtures: Water Source

Public

### Water Supply, Distribution and Fixtures: Water Meter Location (if public)

front of home by street



### Water Supply, Distribution and Fixtures: Approximate water pressure

Not tested, Unknown

Normal residential city water pressure is from 40-80 PSI. Well water systems are typically from 30-50 PSI. Less than 30 PSI may be too low to adequately have enough flow for multiple fixtures in the home running simultaneously. More than 80 should be avoided due to risk of damage to appliances and water distribution lines.

**Water Supply, Distribution and Fixtures: Incoming water line material**

PEX



**Water Supply, Distribution and Fixtures: Water distribution piping material**

CPVC



**Water Supply, Distribution and Fixtures: Winterize hose bibs**


Winterize exterior hose bibs in the colder months to prevent potential freezing and damage to the home. Here are some useful tips.

- Remove your water hose from the hose bib in cold weather
- If the hose bib is not frost free, locate the hose bib shutoff if existing and turn off water to the fixture

**Hot Water Systems, Controls, Chimneys, Flues and Vents: Water heater #1**

Brand: Bradford White  
 Energy type: Gas  
 Location in home: Garage  
 Capacity: 40 gallon  
 Approximate age: 17 years  
 TPR valve present: Yes  
 TPR extension present: Yes  
 Deferred cost: Yes

The typical life expectancy of all water heaters is estimated to be 10-12 years. You can potentially extend the life with yearly maintenance including servicing by a plumber, changing the anode rod(s), and draining the tank to help eliminate sediment (excluding tankless). Water heaters 10 determined to be 10 years and older are marked as deferred cost, and recommended to be budgeted for replacement.



**Hot Water Systems, Controls, Chimneys, Flues and Vents: Water Heater Location**

Garage

**Hot Water Systems, Controls, Chimneys, Flues and Vents: Water Heater Capacity**

40 gallon

**Hot Water Systems, Controls, Chimneys, Flues and Vents: Water Heater Power Source**

Gas (quick recovery)

**Hot Water Systems, Controls, Chimneys, Flues and Vents: Manufacturer**

BRADFORD-WHITE

**Hot Water Systems, Controls, Chimneys, Flues and Vents: Temperature Pressure Relief Valve and Piping**

Present



### Hot Water Systems, Controls, Chimneys, Flues and Vents: Water temperature measured

115-120


Typical hot water temperature range is between 110 and 120. Be aware that temperatures above 120 are considered a scalding hazard and the water heater should be turned down to maintain water temperatures at or below 120 Fahrenheit.



### Main Water Shut-off: Water shutoff location


Coat closet, At meter

You should note your main water shutoff location in case you need to quickly turn off the water in case of emergency. It's always good to test the shutoff to make sure it works properly before you actually need it in an emergency. It's a good idea to test it during normal business hours in case you need a plumber and be ready to shut off water at the meter if a leak develops when testing. If no shutoff is available in the home, and you have a water meter, a T handle water key is a helpful tool to turn the water off quickly. An example of a T handle water key is shown below, and is available at any home improvement store.



### Main Fuel Shut-off: Shutoff at gas meter

The main fuel shut off is at the gas meter on the exterior of the home. Recommend knowing where the shutoff valve is located and having a wrench available to shut off gas quickly in case of an emergency.



Gas shutoff at meter

## Limitations



Water Supply, Distribution and Fixtures

## LIMITATIONS

Ceiling / wall / floor covering, Insulation

There was some limitations on visibility of the water piping or plumbing fixtures. Not all areas were inspected.

Water Supply, Distribution and Fixtures

## IRRIGATION SYSTEM NOT INSPECTED

The home is equipped with an irrigation system. This system is mostly underground and not visible, is beyond the scope of the home inspection, and was not inspected. I recommend an irrigation company test your irrigation system to verify it is working properly and does not have any leaks. You may also need yearly testing of the backflow prevention device by a certified tester. The [Clark County irrigation safety document](#) is a good document for your reference.

**Additional notes:** Monitor and ensure sprinkler heads do not direct water on the home.



Water Supply, Distribution and Fixtures

## WATER PRESSURE NOT TESTED

COULD NOT SCREW PRESSURE GAUGE ONTO HOSE BIB, NON TYPICAL THREADS

There was nowhere to feasibly check water pressure. I did not check the pressure.

## Observations

8.2.1 Water Supply, Distribution and Fixtures

### CAULK / GROUT WORK NEEDED

Multiple areas bathrooms around tubs showers countertops etc

**Issue:** There is missing or failed caulk or grout in some areas where it is necessary to prevent water intrusion. Keep caulk / grout in good condition at countertops, sinks, showers, tubs, and floor areas around tubs and showers to prevent potential water entry in areas around plumbing fixtures. Some areas are in need of maintenance.

**Remedy:** Repair caulk or grout as needed.



Minor Defect / Maintenance / Monitor Item



## 8.2.2 Water Supply, Distribution and Fixtures



Safety Item

**CROSS CONTAMINATION HAZARD**

Shower sprayer hose hangs below tub rim, Bidet

**Issue:** There is a cross contamination hazard that needs correction for safety.**Remedy:** Provide an air gap or have a backflow preventer installed.

**Additional notes and more information:** For health safety reasons, plumbing fixtures such as hose bibs, irrigation systems, dishwashers, sinks, bathtubs, bidets, etc require either backflow prevention devices or an air gap to prevent water being siphoned backwards into the home's water supply. Backflow preventers on hose bibs and irrigation systems are safety devices that prevent water flowing backwards into a home's water supply. An air gap of at least 1 inch for sink and tub faucets above the basin rim also prevents water from being able to flow backwards into the home's water supply in some circumstances.

Condensate drain lines from air conditioners, high efficiency furnaces, and water softeners also need an air gap to prevent contamination of the equipment.

8.2.3 Water Supply,  
Distribution and Fixtures

Minor Defect / Maintenance / Monitor Item

**SLOW DRAINAGE AT FIXTURE**

2ND FLOOR HALLWAY BATHROOM BATHTUB

**Issue:** There is slow drainage at a sink or bathtub. Often, cleaning out the drain or trap can resolve this issue.**Remedy:** Clean out the trap or drain, and if that does not resolve the issue, contact a plumber for repair.8.2.4 Water Supply,  
Distribution and Fixtures

Minor Defect / Maintenance / Monitor Item

**NO PAN UNDER WASHING MACHINE****Issue:** There is no pan under the washing machine. This increases the risk of water damage if the washer leaks.**Remedy:** Have a pan installed under the machine.

8.3.1 Hot Water Systems, Controls, Chimneys, Flues and Vents

 Minor Defect / Maintenance / Monitor Item

**CORROSION ON FITTINGS**

There is some corrosion around the fittings for the water heater where galvanized piping and Copper piping are connected to copper piping causing dissimilar metal corrosion. Recommend monitor and repair as necessary if leaking occurs. You can prevent corrosion by installing dielectric connectors in this location to separate the dissimilar metals.



## 9: HEATING / COOLING SYSTEMS

		SA	NI	NP	RR
9.1	Heating Equipment	X			
9.2	Operating Controls	X			
9.3	Safety Controls	X			
9.4	Distribution Systems and Supporting Equipment				X
9.5	Presence of Installed Heat Source in Each Habitable Room	X			
9.6	Gas/LP Firelogs and Fireplaces	X			
9.7	Chimneys, Flues and Venting (fireplaces, water heaters, heat systems)	X			
9.8	Solid Fuel Heating (Fireplace, Woodstove)			X	
9.9	Cooling Equipment				X

SA = Satisfactory    NI = Not Inspected    NP = Not Present    RR = Repair / Replace

### Information

**Heating Equipment: Heating Equipment Types**

Forced air gas furnace

**Heating Equipment: Heating Equipment Energy Source**

Natural gas

**Heating Equipment: Heat System Brand**

Trane

**Heating Equipment: Number of Heat Systems (excluding wood)**

One

**Heating Equipment: Furnace location**

garage

**Heating Equipment: High-efficiency Gas furnace**

Approx. age in years: 17

This furnace unit is forced air, high efficiency, gas furnace. Typical lifespan of the average gas furnace / heat exchanger is 15 - 20 years. You can identify potential problems and extend the life of your furnace with regular servicing and inspection by an HVAC technician. Certain limitations exist for a visual inspection of the gas furnace including the heat exchanger which is not visible for inspection. We recommend having the furnace's heat exchanger evaluated when it is serviced by an HVAC technician.



**Heating Equipment: (T) Gas furnace normal temp**

Temperature recorded: 119 F, about 46 degree temperature split

The gas furnace was operated using thermostat controls and the output temperature at the register was within normally expected temperature ranges for a furnace of this kind. Typical air temperatures at the register for gas furnaces is around 100-130 degrees at the register. Other variables will affect this temperature such as distance from the furnace, type, age and efficiency of the furnace.



**Heating Equipment: (D) Deferred cost gas furnace**

Approx. age in years: 17

The typical life expectancy of a gas furnace is 15 to 20 years. Due to the age of your furnace I recommend you consider budgeting for a new unit. This does not mean it may fail soon, only that according to industry statistics, it is nearing the end of service life.

**Heating Equipment: Service Status**

Recommend servicing, Service log indicates more than 12 months since last service

Given appearance of the unit, we try and estimate if the unit is due for service and has or has not been maintained.

**Distribution Systems and Supporting Equipment: Ductwork**  
Insulated

**Distribution Systems and Supporting Equipment: Filter Location**  
at the air handler, garage

**Distribution Systems and Supporting Equipment: Filter Type**  
Disposable



**Distribution Systems and Supporting Equipment: Filter Size**  
20x20

**Gas/LP Firelogs and Fireplaces: Number of fireplaces**  
1

**Gas/LP Firelogs and Fireplaces: Types of fireplaces**  
Vented gas logs

**Gas/LP Firelogs and Fireplaces: Gas fireplace operated**

I inspected and operated the gas fireplace. I recommend inspection and servicing of the fireplace yearly to ensure it is operating safely and efficiently. I am unable to see the flue connector and piping for inspection. Be sure and clean under the fireplace yearly to remove dust and cobwebs which could interfere with ignitor operation. For your information, if you are a Northwest Natural gas customer, you can schedule a free inspection and testing of your gas



appliances. Here is a link for more information.

<https://www.nwnatural.com/CustomerService/EquipmentServices/InspectionInformation>



**Solid Fuel Heating (Fireplace, Woodstove): Solid fuel burning appliances**

None

**Solid Fuel Heating (Fireplace, Woodstove): Number of Wood Stoves**

None

**Cooling Equipment: Cooling Equipment Types**

Air conditioner unit

**Cooling Equipment: Number of Cooling Systems**

One

**Cooling Equipment: Cooling Equipment Energy Source**

Electricity

**Cooling Equipment: Cooling Equipment Brand(s)**

PAYNE

**Cooling Equipment: Air conditioner - Unit #1**

Approx. age in years: 7

The home has an air conditioner installed. Typical life expectancy of an air conditioner compressor is 12-15 years.

I recommend yearly servicing by an HVAC technician.



**Cooling Equipment: (T) AC cooling temp normal**

Temperature recorded: 49 F, about 24 degree temperature split

The air conditioner was operated and the temperature at the registers was within the normal expected range (14-22 degrees lower than ambient).



## Observations


9.1.1 Heating Equipment

 Minor Defect / Maintenance / Monitor Item

### RECOMMEND SERVICING

**Issue:** I was unable to determine the last time the HVAC was serviced or it is overdue according to the service log. HVAC heating appliances should be serviced yearly including heat exchanger inspection if they are a gas burning furnace.

**Remedy:** Servicing followed by yearly servicing by an HVAC technician. Yearly servicing helps identify issues earlier and keep the appliance operating in its peak efficiency and performance.



Bus service indicated 2015

9.1.2 Heating Equipment

 Minor Defect / Maintenance / Monitor Item

### PAST LEAKING IN HIGH EFFICIENCY FURNACE CABINET

NO LEAKING NOTED DURING OPERATION AT THE INSPECTION

**Issue:** There is some rust / damage in the high efficiency furnace cabinet indicating past leaking. High efficiency condensate is corrosive.

**Remedy:** Further review by an HVAC contractor along with any necessary repairs.

**Additional notes:** Leaking and rust in the cabinet can damage the equipment and any active leaking repaired promptly.



9.4.1 Distribution Systems and Supporting Equipment

 Minor Defect / Maintenance / Monitor Item

### DUCTWORK NOT PROPERLY SUPPORTED

IMPROPERLY SUPPORTED IN SOME AREAS OF THE CRAWL SPACE

**Issue:** The HVAC ducting is not properly supported on some areas. Ductwork should be supported approximately every 4 feet, should not be laying on the ground, should not be tied to other piping or electrical wiring for support, and not have big sagging areas. This can be conducive to pest entry and damage to the ductwork, and also cause condensation in the duct work from laying on the cold ground. This could potentially lead to moisture related issues in the duct work and pest intrusion.

**Remedy:** Have a contractor repair any areas lacking proper support.



## 9.4.2 Distribution Systems and Supporting Equipment



Minor Defect / Maintenance / Monitor Item

**NO LOCKING REFRIGERANT CAPS AT AC / HEAT PUMP**

**Issue:** There are no locking refrigerant caps on the AC / heat pump compressor. This is to prevent unauthorized access to the refrigerant chemicals.

**Remedy:** Have an HVAC contractor add locking refrigerant caps.

**Recommended time frame:** When unit is next serviced

Example of locking caps



Sample image of locking refrigerant caps



## 9.6.1 Gas/LP Firelogs and Fireplaces



Minor Defect / Maintenance / Monitor Item

**AREA UNDER FIREPLACE NEEDS CLEANING**

**Issue:** Maintenance needed. There is dust and cobwebs under the gas fireplace. Dust and cobwebs may affect operation of the fireplace such as making it difficult to light.

**Remedy:** Clean out dust and cobwebs now. Clean it periodically such as once per year.



## 9.9.1 Cooling Equipment



Minor Defect / Maintenance / Monitor Item

**RECOMMEND SERVICING**

Air conditioners and heat pumps should be serviced yearly. I was unable to determine the last time the air conditioner was serviced. The service log is often visible as a sticker on the air handler and this is where we check for any indication of servicing. The absence of a sticker in a service log on the machine does not necessarily mean it has not been serviced. I recommend servicing at the beginning of the next cooling season or now, as applicable.



9.9.2 Cooling Equipment

 Minor Defect / Maintenance / Monitor Item

**DIRTY COMPRESSOR FINS**

**Issue:** The compressor fins at the AC compressor are dirty and clogged with dust and debris. This will cause the air conditioner to operate at less than optimal efficiency and airflow.

**Remedy:** Have the fins cleaned by an HVAC contractor or any qualified person.

**Recommended time frame:** When feasible

**Additional notes:** Fins can be cleaned with a soft brush and vacuum. Be aware that the fins are very fragile and easily damaged.



Close up of compressor fins clogged with dust and debris



Compressor fins clogged with dust and debris

## 10: INSULATION AND VENTILATION

		SA	NI	NP	RR
10.1	Insulation in Attic				X
10.2	Insulation Under Floor System	X			
10.3	Vapor Retarders (in Crawlspace or basement)	X			
10.4	Ventilation of Attic and Foundation Areas				X
10.5	Venting Systems (Kitchens, Baths and Laundry)				X
10.6	Ventilation Fans and Thermostatic Controls in Attic			X	
10.7	HRV / ERV			X	

SA = Satisfactory    NI = Not Inspected    NP = Not Present    RR = Repair / Replace

### Information

**Insulation in Attic: Attic Insulation types**

About R38 fiberglass, 13 inches

Fiberglass loose fill





**Insulation Under Floor System:  
Floor System Insulation**

Fiberglass batts



**Ventilation of Attic and  
Foundation Areas: Attic  
ventilation**

Soffit Vents, Passive

**Ventilation of Attic and Foundation Areas: Crawlspace ventilation**

Perimeter venting

Underfloor spaces should have approximately 1 square foot of venting for each 150 square feet of floor space unless it is an encapsulated and conditioned area.

**Venting Systems (Kitchens, Baths  
and Laundry): Kitchen exhaust**

Vented

**Venting Systems (Kitchens, Baths  
and Laundry): Dryer vent material**

Metal

**Venting Systems (Kitchens, Baths  
and Laundry): Dryer power**

source

240 Electric

**Venting Systems (Kitchens, Baths and Laundry): Periodic cleaning dryer vent**

Right side

I recommend knowing the location of the dryer exhaust vent and having the vent piping cleaned periodically / yearly as needed to prevent the buildup of lint which can be a fire hazard. Have the dryer vent inspected by a duct cleaner upon move-in to determine if it needs cleaning.



**Observations**

10.1.1 Insulation in Attic

 Minor Defect / Maintenance / Monitor Item

**INSULATION  
DAMAGED FROM FOOT TRAFFIC**

A LITTLE SMASHED DOWN BY HATCH AND IN A FEW SMALL AREAS

**Issue:** The insulation is tamped down in some areas of the attic due to foot traffic. This will result in the loss of efficiency in these areas.

**Remedy:** Redistribute or add insulation in damaged / lacking areas as necessary to bring the insulation back up to other installed levels.



Insulation tamped down from foot traffic

10.2.1 Insulation Under Floor System

 Minor Defect / Maintenance / Monitor Item

### INSULATION FALLING DOWN / MISSING / DAMAGED

STARTING TO FALL DOWN ONE AREA RIGHT SIDE OF CRAWLSPACE

**Issue:** The insulation under the floor is falling down, missing, or damaged in some areas.

**Remedy:** Further review by a crawlspace / insulation contractor and repair as necessary



10.4.1 Ventilation of Attic and Foundation Areas

 Minor Defect / Maintenance / Monitor Item

### ATTIC SOFFIT BAFFLES FALLEN DOWN

MULTIPLE AREAS, BAFFLES FALLEN DOWN

Some of the insulation baffles at the soffits have fallen down. I recommend they be re-installed to hold insulation back from blocking the soffit vents.



10.5.1 Venting Systems (Kitchens, Baths and Laundry)

 Safety Item

### DRYER VENT LINT BUILDUP

LINT STARTING TO BUILD UP AT LOUVERS

**Issue:** There is visible lint buildup in the dryer exhaust duct work. It is not always possible to see the entire length of the dryer duct, often only a small portion is visible. Lint buildup in a dryer duct is a fire hazard.

**Remedy:** Having the dryer duct cleaned by a duct cleaner.

**Recommended time frame:** Immediate



10.5.2 Venting Systems (Kitchens, Baths and Laundry)



**SCREEN ON DRYER EXHAUST DUCT**

SCREEN HAS FALLEN OFF, DO NOT REPLACE

**Issue:** There is a screen covering the dryer duct exit which is a fire hazard. Screens should never be installed on dryer ducts because they can allow lint to build up and become a fire hazard.

**Remedy:** Have the screen removed and / or a proper louvered damper installed.

**Recommended timeframe:** Immediate



Here's the screen laying on the ground that fell off of the dryer vent termination  
Dryer vent on right side of home

## 11: BUILT-IN KITCHEN APPLIANCES

		SA	NI	NP	RR
11.1	Dishwasher	X			
11.2	Ranges/Ovens/Cooktops				X
11.3	Range Hood (s)	X			
11.4	Trash Compactor			X	
11.5	Food Waste Disposer	X			
11.6	Microwave Cooking Equipment				X
11.7	Built in refrigerator			X	

SA = Satisfactory    NI = Not Inspected    NP = Not Present    RR = Repair / Replace

### Information

**Dishwasher: Aged dishwasher**

The dishwasher is an aged appliance, and due to it's apparent age, I recommend budgeting for a new unit.

**Ranges/Ovens/Cooktops: Aged range / ovens**

The range/oven is an aged appliance, and due to it's age, and I recommend budgeting for a new unit.

**Ranges/Ovens/Cooktops: Range / oven was operational**

The range / oven operated as expected.



**Microwave Cooking Equipment: Aged microwave**

The microwave is an aged appliance, and due to its apparent age, I recommend budgeting for a new unit.

**Built in refrigerator: Non-built-in refrigerator checked as a courtesy**

Temperatures for their refrigerator and freezer were checked and found to be normal. For non-built-in appliances it is not a requirement to inspect them but this was done as a courtesy.



**Observations**

11.2.1 Ranges/Ovens/Cooktops

**NOISY FAN**

The oven fan is noisy and may have bearings failing. Have an appliance technician review it for repair.

 Minor Defect / Maintenance / Monitor Item

11.6.1 Microwave Cooking Equipment

**LIGHT UNDER MICROWAVE INOP**

The light under the microwave is not operable and needs repair.

 Minor Defect / Maintenance / Monitor Item





## 12: MISCELLANEOUS

		SA	NI	NP	RR
12.1	Radon		X		
12.2	Hazardous materials		X		
12.3	Pest Activity		X		
12.4	Bollards	X			
12.5	Permitting / Due Diligence		X		
12.6	Hazardous conditions		X		

SA = Satisfactory    NI = Not Inspected    NP = Not Present    RR = Repair / Replace

## Information

### Radon: Radon resistant construction

This home has Radon resistant new construction in place. There is Radon vent piping installed in the home in case it becomes necessary to make it an active Radon mitigation system in the future. This is not an active Radon mitigation system.



Radon piping in the crawl space

### Hazardous materials: House built in 1978 or before indicating potential for lead paint?

No - built after 1978

Be aware that homes and structures built in 1978 and before may contain lead paint. Lead paint was commonly used up until 1978 until it was banned due to the potential harmful health effects of ingesting lead. If unknown, it is always advisable to have paint tested for lead before scraping, grinding, or sanding that could generate the potential for ingestion.

### Hazardous materials: Potential Asbestos containing materials observed?

No - none noted

Asbestos was a very common ingredient in older building materials. It is strong, fire resistant, and was contained in many building materials such as siding, flooring, HVAC insulation and wrap, and many others. Asbestos is dangerous if it is inhaled and the Asbestos fibers get stuck in the sensitive linings of the lungs and is a known cancer causing substance. Before demolishing, removing, or disturbing interior building materials such as flooring, ceiling tiles, HVAC sleeving or wrapping, countertops, lathe and plaster, drywall tape, or wall coverings, it is advisable to have them tested for Asbestos to ensure the items you are disturbing are safe to do so.

### Pest Activity: Pest preventative measures in / around home

Rodent trap in crawlspace

There are some pest preventative measures installed in or around the home. I recommend consider asking the seller for more information regarding this item as I am unable to determine if pests are present. Consult with a pest control operator if necessary.

**Pest Activity: Was there any potential pest activity noted?**

No - none noted

Potential pest activity was noted in some areas of the home. Inspector is not a licensed pest inspector and able to diagnose exact tests or treatment. Consult with a pest control operator for more information.

**Permitting / Due Diligence: Permitting / Due Diligence**

Checking on permitting for construction work, changes, alterations, additions, to any system or component in the home is not part of the home inspection and was not performed. Any due diligence regarding permitting is the responsibility of the customer to perform.

All recommendations for repairs should be further reviewed by licensed contractors during your contingency period for additional information regarding scope of work and cost associated.

## Limitations

---

Pest Activity

**PEST / WDO INSPECTION WAS NOT PERFORMED**

We are not licensed, trained for, nor do we perform a pest or Wood Destroying Organism (WDO) inspection during the home inspection. WDO is disclaimed, and is not a part of the home inspection.

## Observations

---

## 12.6.1 Hazardous conditions

**CROSS CONTAMINATION HAZARD**

MASTER BATHROOM, 2ND FLOOR HALLWAY BATHROOM

Sprayer / hose at toilet, Hose / sprayer on faucet below sink rim

**Issue:** There is a potential cross contamination hazard. Cross contamination hazards exist when there is a potential for the building's water supply to be contaminated by things such as bacteria. Plumbing fixtures and other appliances such as dishwasher drains, clothes washer drains, and AC condensate drain lines, must have an air gap below where it drains / fills to prevent potential cross contamination of the potable water supply. There is a fixture or other item that needs correction to prevent health hazards from potential cross connection.

**Remedy:** Provide an air gap or remove the item, verify the device has a built in backflow preventer, replace device with one having a known backflow preventer.

**Notes:** some devices or fixtures may have a built in backflow preventer. Examples of that would be shower hand sprayers or bidet sprayers. It is not able to be determined just by looking at the item. You can try looking up the part or item to determine if it has a built in backflow preventer, remove the item, or replace with one having a backflow preventer.



# 13: ADDITIONAL INFORMATION

## Information

### Standards of Practice


#### Home Inspector Requirements / Standards of Practice

Home inspectors are required to follow state mandated standards of practice as applicable and be licensed in any state that requires licensing. We adhere to published standards in Washington and Oregon state for home inspectors. Detailed state standards of practice can be found online for the appropriate state. Areas inspected include Roof, Exterior, Drainage / Grading as related to the home, Attached garages, Attic, Basement, Crawlspace, Structural features, Electrical, Plumbing, HVAC, Interior, and Built in kitchen appliances.

Home inspectors are not required to report on the following: Life expectancy of any component or system; The causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items, or items not permanently installed. Home inspectors are not required to: Offer warranties or guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; Predict future condition, including but not limited to failure of components. Since this report is provided for the specific benefit of the customer(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

### Navigating The Online Report

#### How To Navigate the Online Version of the Home Inspection Report



**1. Filters** - These are your filters that will condense the HTML report to only what you want to see. You can filter by all deficiencies/recommendations,

General Summary, or just by Safety items

**2. Sidebar Navigation** - Sidebar navigation that allows you to jump to any section right away.

**3. PDF Button** - This button is used generate a complete or summary PDF version of the report.

### Commonly Used Terms

#### Commonly Used Terms



**Deferred cost:** Systems or components costing significant amounts of money that are estimated or appear to be within 3 years of the typical lifespan. This does not mean the system or component is defective, however, given the appearance or known age, you should consider budgeting for a replacement because it may be nearing end of life. There is no guarantee that the component will or will not fail, just statistically, it is within a few years of typical lifespan.

**Monitor:** Items that are recommended to be periodically inspected for any changes that may require further action or repair.

**Repair / Replace:** Items or systems that are not functioning as intended and need either repair or replacement by a contractor.

**Further review:** Items or systems that should be reviewed by a contractor to determine extent of repair necessary as they may have significant cost or affect the negatively affect the structure. If you are having this inspection done for purchasing a home, it is strongly recommended to have contractors perform further reviews during your contingency period to obtain relevant cost and information regarding repairs.

**Safety:** Items in the opinion of the inspector that are safety related and pose a current or potential risk to people in or around the home.

## Expectations

### Expectations

Evaluating a home is a huge investment and a very involved project. We understand that, and take our role in the process very seriously. Our goal is to meet and exceed your expectations in every way in our inspection services. It is very important that we the inspectors, and you, the customer are on the same page with expectations and what our role is in the inspection process. This includes our limitations and what we can safely and feasibly accomplish in the limited amount of time we have in the home.

Please understand that the visual home inspection is a quick snapshot in time at the time of the inspection with observations being made only at the time of inspection. The inspector cannot determine future or past occurrences or events.

Also please realize that inspectors only have a short amount of time in and around a home to inspect many areas, systems, and components. The inspector tries to identify as many items of concern of interest to you as is feasible possible given the time allowance, however, be aware that after moving in, you may notice things the inspector did not notice or chose not to identify. The inspection is not exhaustive, and it is impossible to figure out everything about a home in a short amount of time. The goal is to find and identify relevant material defects. Ie, the inspectors are after the big defects, the Marlin, not the minnows. Material defects are the items that are decision making kinds of things. Examples of those would be things like a roof that is at the end of its useful life, or a structural problem with the foundation.


Occupied homes pose a challenge in that many areas are not visible for inspection such as walls, floors, cabinets, closets, and garages because storage or personal items block visibility. Home inspectors do not move people's belongings or storage items. Thus, areas covered by belongings, furniture, or storage are not visible are not able to be inspected.

Occasionally, we have limitations which prevent a full inspection of an item or area that we would like to inspect. Safety is also a top priority. Sometimes it is not safe or feasible to attempt to inspect or access an area. Examples of this would be water in the crawlspace limiting safe access, high or steep roofs which pose a fall hazard, belongings blocking access to an area like the attic or electrical panel, systems that have been shut down like furnaces or water heaters, or excessive animal droppings in crawlspaces that pose a health hazard. We will do everything we can to safely and feasibly perform a thorough inspection, and if there are limitations, we will convey that to you in our report along with the reason for the limitation. We are always happy to return to the home in a repeat visit to inspect the items that we could not feasibly or safely inspect once the reason for the limitation is resolved. An example of this would be the wine rack has been removed from covering the crawlspace entry hatch. Repeat visits are subject to additional charges and sometimes difficult to fit into the schedule, but we are always happy to do them to provide a more thorough inspection for our customers.

The bottom line is that we care about your satisfaction with our services, take great pride in our inspection services, and are going to do everything we possibly can to identify as many relevant items for you during our limited time in the home. It's not possible to find everything in a home given our limited time, but we will always give you 100% effort and diligence.

I want to say thank you very much for choosing 45th Parallel for your home inspection needs. We appreciate you. If you ever have any questions, concerns, or comments, we want to hear from you. Let us know if there is anything that we can further assist you with.

All the best,

A handwritten signature in cursive script that reads "Russell Tolle". The signature is written in black ink and is positioned below the text "All the best,".

Russell Tolle  
Owner, 45th Parallel LLC